

IECEX Quality Assessment Report Summary: GB/ITS/QAR12.0012/04 details

QAR Summary :				
QAR Reference Number *: (automatic numbering)	GB/ITS/QAR12.0012/04			
Related QARs:	GB/ITS/QAR12.0012/03 GB/ITS/QAR12.0012/02 GB/ITS/QAR12.0012/01 GB/ITS/QAR12.0012/00			
Status*:	Issued			
QAR Free Reference Number*:	G103525708 G101677864UK			
Audit Date*: (yyyy-mm-dd)	2018-07-18			
Date of Issue*: (yyyy-mm-dd)	2018-11-08			
Details of change*:	Reassessment of manufacturer with a certified QMS Removed protection techniques: Encapsulation (m) Intrinsically Safe (i.b.)			
Valid until*: (yyyy-mm-dd)	2021-07-11			
Site(s) audited*:	Tideland Signal Corporation, 4310 Directors Row, Houston, Texas 77092. USA			
Issuing ExCB*:	ITS - Intertek Testing & Certification Limited			
Manufacturer*:	Tideland Signal Corporation, 4310 Directors Row, Houston, Texas 77092.			
Location of Manufacture*:	United States of America			
Product information*:	Manufacturer Of Aids To Marine Navigation Equipment And Systems			
Protection concept*:	Flameproof 'Ex d' Increased Safety 'Ex e' Purge and Pressurization 'Ex p' Type n			
Related IECEX Certificates: (automatic linking)				
Related Certificates: (manual insertion)				
Related IECEX Certificates for previous versions:				
	ExCB	CoC and Status	Totals	
	▼ BAS			1
		IECEX BAS 14.0149 issue: 0 [Cancelled]		
	▼ ITS			14
		IECEX ITS 14.0019X issue: 0 [Current]		
		IECEX ITS 14.0019X issue: 1 [Current]		
		IECEX ITS 14.0019X issue: 2 [Current]		

[IECEX ITS 15.0058X issue: 0 \[Current\]](#)

[IECEX ITS 15.0069X issue: 0 \[Current\]](#)

[IECEX ITS 15.0069X issue: 1 \[Current\]](#)

[IECEX ITS 15.0069X issue: 2 \[Current\]](#)

[IECEX ITS 16.0007X issue: 0 \[Current\]](#)

[IECEX ITS 16.0007X issue: 1 \[Current\]](#)

[IECEX ITS 16.0016X issue: 0 \[Current\]](#)

[IECEX ITS 16.0016X issue: 1 \[Current\]](#)

[IECEX ITS 16.0017X issue: 0 \[Current\]](#)

[IECEX ITS 16.0017X issue: 1 \[Current\]](#)

[IECEX ITS 16.0017X issue: 2 \[Current\]](#)

▼ SIR

1

[IECEX SIR 15.0117X issue: 0 \[Suspended\]](#)

▼ UL

2

[IECEX UL 15.0050X issue: 0 \[Current\]](#)

[IECEX UL 15.0050X issue: 1 \[Current\]](#)

18

Comment:

Tideland is moving to a new location in 2019.
Tideland Signal Corporation
7100 Business Park Drive, Suite B
Houston, TX 77041, USA.

Attachment: